



PO Box 1150  
Issaquah, WA 98027  
(206) 965-5797

## J. Jeffrey Huber Daily Report

10-22-2020

River Activities – None.

Construction Activities – Electron Crew working on placing rocks, backfilling, and erosion control.

JH – 0700 Electron crew member Bruce conducting water quality monitoring.

JH – 0700 Electron crew member 300' downstream to monitor turbidity.

JH – 0700 electron crew begins putting in rip rap. The rip rap is then filled with fines and smaller rock to ensure no voids.

JH – 0800 Electron crew working on the overflow and rock screen on the flume near the intake.

JH – Electron crew is grouting the center abutment. They are specifically grouting the holes from the plywood forms used to construct the center abutment.

JH – 1045 Corps of Engineers, Puyallup Tribe Fisheries, and other assorted folks on deck at the intake.

JH – 1100 Electron crew placing rip rap. This will be on going through the day and will follow into tomorrow

JH – Electron crew back filling around the center abutment with large rocks.

JH – Electron crew working on placing organic wood chips on slopes and exposed ground this will be on going

JH – 1500 – 1800 observed fish ladder. Nothing to report and no issues.



PO Box 1150  
Issaquah, WA 98027  
(206) 965-5797

Sincerely,

J. Jeffrey Huber  
Encore Environmental  
Independent Compliance Monitor on Behalf of Pierce County  
Electron Hydro